


Making Ship's Boats Part 2

























Disadvantages:

- Wrinkle at bow must be repaired
- Very thin, weak at top
- Keel not built in

New Method-Coating a onepart Mold













рт.

PAFH I

NA L

, 189

-





Disadvantages:

Hull thickness varied

Must use glue to attach innards

Making Ship's Boats